




FIG. 1




F16, 2

TIG, 3








Queue	Priority	_
1	1	
2	2	_
3	3	
4	4	_
5	5	_
6	6	_
7	7	_
8	8	

Queue	Priority
1	6
2	7
3	8
4	1
5	2
6	3
7	4
8	5

FIG. 7A

FIG. 7B



F1G, 8